

OBDSTAR Update Announcement of July 2018

OBDSTAR Update Announcement of July 2018 refer to the devices of [OBDSTAR DP PAD](#), [X300 DP Plus](#), [P001 programmer](#) etc.

IMMO

Toyota/Lexus

Optimize type 8 support car list

Isuzu

Increased D-MAX/MU-X remote programming

Holden

Increased pincode reading function

Increased Barina C IMMO system

Increased Barina MJ IMMO system

Increased Barina Spark IMMO system

Increased Barina TK IMMO system

Increased Barina TM IMMO system

Increased Berlina IMMO system

Increased Colorado RG IMMO system

Increased Frontera IMMO system

Increased Rodeo TF IMMO system

Increased Trax IMMO system

Increased Jackaroo IMMO system

Increased Viva IMMO system

Increased VE Commodore IMMO system

Increased VF Commodore IMMO system

Increased VR Commodore IMMO system

Increased VS Commodore IMMO system

Increased VT Commodore IMMO system

Increased VX Commodore IMMO system

Increased VU IMMO system

Increased VY Series 1 IMMO system

Increased VY Series 2 IMMO system

Increased VZ Series 1 IMMO system

Increased WH Statesman IMMO system

Increased WK Statesman IMMO system

Increased WL Statesman IMMO system

Increased WH Caprice IMMO system

Increased Barina B remote control system
Increased Barina TK remote control system
Increased Barina Spark remote control system
Increased Viva remote control system
Increased VE Commodore remote control system
Increased type 1-6

BMW

Optimize all keys lost programming problems

Nissan

Solve ISO communication unstable problem

VW/Audi/Skoda/Seat

Solved Audi RB4/RB8 IMMO bug
Solved Audi A3/TT EEPROM backup problem
Increased the function of clear fault code for dashboard and air bag

Zotye

Increased T700 smart key system
Increased Zotye E200 smart key system
Increased T500 remote control system and smart key system
Increased Dany X7 remote control system and smart key system

Chrysler

Optimize Jeep Free Light 2014-transponder key and smart key

Ford

Optimize Europe FORD Transit 07-14 Erase key function

Renault

Increased Fluence/Latitude/Avantime/Duster/Master/Symbol

Combined the pincode and pincode free menu with auto select function

Geely/SMA/Englon

Optimize Geely Boyue key programming text tip

Renault/Dacia/Lada

Solved Fluence type vehicles pincode reading mode auto select error
Solved Symbol (2013-2018) type vehicles pincode reading problem

Increased DOKKER/LODGY/LOGAN 2013-/SANDERO 2013-/ SYMBOL

2013-2018(DUSTER2014-2018)

GM

Optimized Cadillac XTS key programming (solved the bug: compulsory to wait for 12minutes)

Remote Control Manual Setting

Increased English, Russian, Thai, Portuguese, Turkish, Spanish, Indonesian, Polish, Persian, French

EPB

New Increased:

FAW:Besturn X80F

BAIC MOTOR:BJ20

Baihc Hyosow:S5/S6

Zotye:Damy X7/Z300

Land Rover: New Range Rover(2017)

GAC Trumpchi : GS4/GS8/GS7/GM8/GS4-2018

SAIC MG:New GS/MG6 EU(2014)/MG6 TT(2015)

GAC Honda:ACCORD/CIVIC/FIT/ODYSSEY/EVERUS S1CRIDER

Geely: EMGRAND X6(2018)/EMGRAND EV series (EV300/EV450)

Changan: CS95(S401)/CS55(S201)/RAETON CC(C301)/Oshan/X70A

Changcheng: Hover H2/Hover H2s/Hover H4/Hover H7/H7L/Hover H6/Hover H6

COUPLE/VV5/VV7/P8

Optimize VW/Skoda/Audi

Solved Mercedes-Benz S600 (222-S series) communication failure

Oil/service Reset

New increased in Auto Reset

Roewe: E16/I6

Geely: New Vision (2018) / Vision X3

Skoda: CITIGO/FELICIA/RAPID/YETI/ROOMSTER

Seat: ALHAMBRA/ALTEA/CORDOBA/AROSA/EXEO/IBIZA/INCA/MII/TOLEDO

Zotye: T700/Z700/Damy X7/SR9/T600 Sport/Sesame E30/SR7 (2017) /T600 Coupe/T300

Changcheng: Changcheng C30EV/Changcheng CH041E/Hover H4/Hover M6/VV5/VV7/P8

Hyundai:

ACCENT/CRETA/CELESTA/ELANTRA/ELANTRA/GRANDEUR/AZERA/G80(DH)/G90(HI)/HB20(HB)/i30/i40/IONIQ electric(AE EV)

IONIQ hybrid(AE HEV)/IONIQ/PHEV(AE PHEV)/ ix25(GC)/NEW VERNA/RV VERNA/SANTAFE/SONATA/ VELOSTER (FS)

KIA:

BORreed/Carnival/Ceed(JD)/K2(UC)/KX3(KC)/K4(PFC)/KX5(QLC)/K5

HEV(JFC

HEV)/Niro/Optima/PICANTO/MORNING/Rio/Sorento/ Sportage/Stinger

Renault:

CAPTUR/QM3/KABIN/CAPTUR(Brazil/India/Russia)/Clio III/Clio IV/ESPACE V/KANGOO II/KANGOO ZE/StopStart/PH2/Koleos II(QM6 China)

Koleos II(QM6)/MASTER III/Megane II/MEGANE III/SCENIC III/Megane IV/MEGANE IV SEDAN/MODUS/NEW SM3/FLUENCE/MEGANE/SCENIC II

SCENIC IV/SM7-L47/TALISMAN(SM6)/ TWINGO II/TWINGO III/WIND/ZOE

New increased in Manual Reset

Honda:

CRV(2017-/2018(low configuration)/2018(high configuration)/CR-Z(2012)/Integra(1992-1993/1994-1995/1996-2001)/

JADE(2017)/Legend(1992-1995)/Vigor(1992-1994)/Civic(2015-)

Jeep/Dodge/Chrysler: updated the vehicle menu as follow:

MK-Compass/Patriot 2007-2014

WK-Grand Cherokee 2006-2017

KK-Liberty 2014-2015

JK-Wrangler 2014-2017

J8-Wrangler 2016-2017

JS-Avenger/Sebring 2007-2014

LA-Challenger 2015-2017

LD-Charger 2014-2017

WD-Durango 2014-2017

JC-Journey 2008-2017

RT-Caravan/Town & Country 2014-2017

ZH-Crossfire(NAFTA) 2007-2008

RU-CHRYSLER PACIFICA 2017

D2-Ram 3500 Pickup 2010-2017

DF-Ram 3500 Cab Chassis 10K 2016-2017

DJ-Ram 2500 2010-2017

DP-4500/5500 2011-2017

DD-3500 Cab Chassis 2011-2017

DS-Ram 1500 2014-2017

MP 2017

M4-Compass(China) 2017

M1-Compass(Brazil) 2017

New added vehicles as follow:

M6-556 2016-2017

LC-Challcnger 2014

KL-Cherokee 2014-2017

JF-Freemont 2011-2017

FF-500 2012-2017

FB-500X 2016-2017

BU-Renegade 2016-2017

BQ-JEEP (China) 2016-2017

BF-Fiat 500L 2014-2017

B1-Renegade 2015-2017

Optimization

Combined Jeep/Dodge/Chrysler vehicle menu

Optimized the following Jeep/Dodge/Chrysler vehicles:Ram Pickup/Jeep compass/Wrangler/Charger/Nitro/Intepid/Vison/Aspen

Steeling Angel Learning

Solved Subaru flash back problem in steeling angel reset

Battery Matching

Optimize BMW 5 series battery matching function

Oil/service Reset

Added the manual reset in part of Jeep vehicles

Solved Changan CS15 oil/service reset failure problem

Airbag Reset

Increased Indonesian language

Increased multi-language translation text

P001 Adapter

Solved P001 adapter PIC Initialization problemmatch

Switch Activation (For OBDDSTAR DP plus)

Increased Porsche Macan dashboard activation function

Increased Lamborghini LP750 dashboard activation function

Increased Ford Mondeo CHIA-X dashboard activation function

Increased Range Rover LCD low speed dashboard activation function

ECU Clone (For OBDDSTAR DP plus)

Optimized communication time during EEPROM and FLASH writing

DP Display Program

Solved Audi RB4/RB8 IMMO bug

Solved NISSNA OLD OBD14 bug: no clock output

Solved NISSNA OLD Nissan_RecvFrame function received bug

www.eobdtool.co.uk